

BLACHA #3

ZMIANA PROMIENIA GIĘCIA WEWN. R16=>R10 + ELEMENT DZIELONY:

- B/21/0061-V-4810-W-M.1-R-3.08_w02 POZ 36

ZMIANA PROMIENIA GIĘCIA WEWN. R16=>R15

- B/21/0061-V-4810-W-M.1-R-4.08_w02 POZ 13

BLACHA #6

ZMIANA PROMIENIA GIĘCIA WEWN. R16=>R15

- B/21/0061-V-4810-W-M.1-R-3.07.14_w02 POZ 4
- B/21/0061-V-4810-W-M.1-R-3.07.14_w02 POZ 5
- B/21/0061-V-4810-W-M.1-R-3.07.14_w02 POZ 6
- B/21/0061-V-4810-W-M.1-R-3.07.15_w02 POZ 2
- B/21/0061-V-4810-W-M.1-R-3.07.17_w02 POZ 1
- B/21/0061-V-4810-W-M.1-R-3.07.17_w02 POZ 2
- B/21/0061-V-4810-W-M.1-R-3.07.17_w02 POZ 3
- B/21/0061-V-4810-W-M.1-R-3.07.17_w02 POZ 4
- B/21/0061-V-4810-W-M.1-R-3.07.18_w02 POZ 2
- B/21/0061-V-4810-W-M.1-R-3.07.18_w02 POZ 1
- B/21/0061-V-4810-W-M.1-R-3.07.18_w02 POZ 3
- B/21/0061-V-4810-W-M.1-R-3.07.19_w02 POZ 1
- B/21/0061-V-4810-W-M.1-R-3.07.21_w02 POZ 3
- B/21/0061-V-4810-W-M.1-R-3.07.22_w02 POZ 1
- B/21/0061-V-4810-W-M.1-R-3.07.22_w02 POZ 2
- B/21/0061-V-4810-W-M.1-R-3.07.22_w02 POZ 3
- B/21/0061-V-4810-W-M.1-R-3.07.23_w02 POZ 1
- B/21/0061-V-4810-W-M.1-R-3.07.23_w02 POZ 2
- B/21/0061-V-4810-W-M.1-R-3.07.23_w02 POZ 3
- B/21/0061-V-4810-W-M.1-R-3.07.25_w02 POZ 1
- B/21/0061-V-4810-W-M.1-R-4.01_w02 POZ 10
- B/21/0061-V-4810-W-M.1-R-3.07.17_w02 POZ 5
- B/21/0061-V-4810-W-M.1-R-3.07.10_w02 POZ 1
- B/21/0061-V-4810-W-M.1-R-3.07.10_w02 POZ 2
- B/21/0061-V-4810-W-M.1-R-3.07.10_w02 POZ 3
- B/21/0061-V-4810-W-M.1-R-3.07.10_w02 POZ 4
- B/21/0061-V-4810-W-M.1-R-3.07.10_w02 POZ 5
- B/21/0061-V-4810-W-M.1-R-3.07.10_w02 POZ 6
- B/21/0061-V-4810-W-M.1-R-3.07.11_w02 POZ 1
- B/21/0061-V-4810-W-M.1-R-3.07.11_w02 POZ 2
- B/21/0061-V-4810-W-M.1-R-3.07.13_w02 POZ 1
- B/21/0061-V-4810-W-M.1-R-3.07.13_w02 POZ 2
- B/21/0061-V-4810-W-M.1-R-3.07.13_w02 POZ 5
- B/21/0061-V-4810-W-M.1-R-3.07.13_w02 POZ 3
- B/21/0061-V-4810-W-M.1-R-3.07.13_w02 POZ 4

- B/21/0061-V-4810-W-M.1-R-3.07.14_w02 POZ 1
- B/21/0061-V-4810-W-M.1-R-3.07.14_w02 POZ 1
- B/21/0061-V-4810-W-M.1-R-3.07.14_w02 POZ 2
- B/21/0061-V-4810-W-M.1-R-3.07.14_w02 POZ 3
- B/21/0061-V-4810-W-M.1-R-3.07.03_w02 POZ 1
- B/21/0061-V-4810-W-M.1-R-3.07.03_w02 POZ 2
- B/21/0061-V-4810-W-M.1-R-3.07.03_w02 POZ 5
- B/21/0061-V-4810-W-M.1-R-3.07.03_w02 POZ 3
- B/21/0061-V-4810-W-M.1-R-3.07.03_w02 POZ 4
- B/21/0061-V-4810-W-M.1-R-3.07.07_w02 POZ 1
- B/21/0061-V-4810-W-M.1-R-3.07.07_w02 POZ 2
- B/21/0061-V-4810-W-M.1-R-3.07.05_w02 POZ 1
- B/21/0061-V-4810-W-M.1-R-3.07.05_w02 POZ 2
- B/21/0061-V-4810-W-M.1-R-3.07.05_w02 POZ 3
- B/21/0061-V-4810-W-M.1-R-3.07.04_w02 POZ 1
- B/21/0061-V-4810-W-M.1-R-3.07.04_w02 POZ 2
- B/21/0061-V-4810-W-M.1-R-3.07.04_w02 POZ 4
- B/21/0061-V-4810-W-M.1-R-3.07.04_w02 POZ 3
- B/21/0061-V-4810-W-M.1-R-3.07.04_w02 POZ 5
- B/21/0061-V-4810-W-M.1-R-3.07.06_w02 POZ 2
- B/21/0061-V-4810-W-M.1-R-3.07.06_w02 POZ 1
- B/21/0061-V-4810-W-M.1-R-3.07.06_w02 POZ 2
- B/21/0061-V-4810-W-M.1-R-3.07.06_w02 POZ 3
- B/21/0061-V-4810-W-M.1-R-3.07.09_w02 POZ 1
- B/21/0061-V-4810-W-M.1-R-3.07.09_w02 POZ 2
- B/21/0061-V-4810-W-M.1-R-3.07.09_w02 POZ 3
- B/21/0061-V-4810-W-M.1-R-3.07.09_w02 POZ 4
- B/21/0061-V-4810-W-M.1-R-3.07.09_w02 POZ 5

ZMIANA PROMIENIA GIĘCIA WEWN. R20=>R10

- B/21/0061-V-4810-W-M.1-R-3.08_w02 POZ 31

BLACHA #8

ZMIANA PROMIENIA GIĘCIA WEWN. R16=>R15 + ELEMENT DZIELONY

- B/21/0061-V-4810-W-M.1-R-3.01.13_w02 POZ 4
- B/21/0061-V-4810-W-M.1-R-3.01.13_w02 POZ 5
- B/21/0061-V-4810-W-M.1-R-4.01_w02 POZ 1

ZMIANA PROMIENIA GIĘCIA WEWN. R16=>R10 + ELEMENT DZIELONY

- B/21/0061-V-4810-W-M.1-R-3.06_w02 POZ 2
- B/21/0061-V-4810-W-M.1-R-4.09_w02 POZ 1
- B/21/0061-V-4810-W-M.1-R-2.04_w02 POZ 2
- B/21/0061-V-4810-W-M.1-R-2.06_w02 POZ 2

ZMIANA PROMIENIA GIĘCIA WEWN. R16=>R15

- B/21/0061-V-4810-W-M.1-R-3.01.14_w02 POZ 3
- B/21/0061-V-4810-W-M.1-R-3.01.14_w02 POZ 6
- B/21/0061-V-4810-W-M.1-R-3.01.14_w02 POZ 4
- B/21/0061-V-4810-W-M.1-R-3.01.14_w02 POZ 7
- B/21/0061-V-4810-W-M.1-R-3.01.14_w02 POZ 5
- B/21/0061-V-4810-W-M.1-R-3.01.16_w02 POZ 1
- B/21/0061-V-4810-W-M.1-R-3.01.16_w02 POZ 2
- B/21/0061-V-4810-W-M.1-R-3.01.16_w02 POZ 3
- B/21/0061-V-4810-W-M.1-R-3.01.16_w02 POZ 2
- B/21/0061-V-4810-W-M.1-R-3.01.17_w02 POZ 1
- B/21/0061-V-4810-W-M.1-R-3.01.17_w02 POZ 2
- B/21/0061-V-4810-W-M.1-R-4.01_w02 POZ 2
- B/21/0061-V-4810-W-M.1-R-4.01_w02 POZ 3
- B/21/0061-V-4810-W-M.1-R-4.01_w02 POZ 4
- B/21/0061-V-4810-W-M.1-R-4.01_w02 POZ 5
- B/21/0061-V-4810-W-M.1-R-4.01_w02 POZ 6
- B/21/0061-V-4810-W-M.1-R-4.01_w02 POZ 8
- B/21/0061-V-4810-W-M.1-R-4.01_w02 POZ 9
- B/21/0061-V-4810-W-M.1-R-4.01_w02 POZ 7
- B/21/0061-V-4810-W-M.1-R-2.02.01_w02 POZ 5
- B/21/0061-V-4810-W-M.1-R-2.02.01_w02 POZ 4
- B/21/0061-V-4810-W-M.1-R-2.02.01_w02 POZ 6
- B/21/0061-V-4810-W-M.1-R-2.02.01_w02 POZ 7
- B/21/0061-V-4810-W-M.1-R-2.02.01_w02 POZ 8

ZMIANA PROMIENIA GIĘCIA WEWN. R16=>R10

- B/21/0061-V-4810-W-M.1-R-4.09_w02 POZ 2
- B/21/0061-V-4810-W-M.1-R-2.08_w02 POZ 4
- B/21/0061-V-4810-W-M.1-R-2.08_w02 POZ 5
- B/21/0061-V-4810-W-M.1-R-2.03_w02 POZ 2
- B/21/0061-V-4810-W-M.1-R-2.06_w02 POZ 3
- B/21/0061-V-4810-W-M.1-R-3.06_w02 POZ 3

BLACHA #10

ZMIANA PROMIENIA GIĘCIA WEWN. R32=>R35

- B/21/0061-V-4810-W-M.1-R-4.01_w02 POZ 11
- B/21/0061-V-4810-W-M.1-R-4.01_w02 POZ 12

BLACHA #16

ZMIANA PROMIENIA GIĘCIA WEWN. R44=>R50

- B/21/0061-V-4810-W-M.1-R-3.01.10_w02 POZ 4 – R44=>R50
- B/21/0061-V-4810-W-M.1-R-3.01.10_w02 POZ 4 – R44=>R50